

# **Customer Information Notification**

Issue Date: 13-Aug-2020 Effective Date: 14-Aug-2020

## 202005006I



## **Management Summary**

There is a issue in SW L4.19 release. We should notice customers to use correct version and avoid issue.

## **Change Category**

☐ Wafer Fab	Assembly	Product Marking	□ Test	Design
Process	Process	_	Location	•
□ Wafer Fab	☐ Assembly	Mechanical	□ Test	☐ Errata
Materials	Materials	Specification	Process	
□ Wafer Fab	☐ Assembly		□ Test	Electrical
Location	Location	Packing/Shipping/Labeling	Equipment	spec./Test coverage
Firmware	Other - So	ftware		

Wrong Voltage Setting and Risk Burning 845/815 on 4.19.xx and 5.4.xx Linux and Android Pre-build Demo Image

## Description

LDO1/2 voltage of rohm,bd71847 are set wrong on L4.19 after kernel bootup:

LDO1@3.0V --NVCC\_SNVS\_1V8 LDO2@0.9V ----VDD\_SNVS\_0V8

With the below kernel print log:

[ 0.931167] Ido1: Bringing 1800000uV into 3000000-3000000uV

[ 0.938256] Ido2: Bringing 800000uV into 900000-900000uV

The issue is impacting 8MMINILPD4-EVK, MX8MMINID4-EVK and MX8MNANOD4-EVK boards. The wrong voltage is vialating the spec and might damage IOs.

The related SW release were set invalid in website after May. 28th

Suggesting customer use latest SW release or apply proper patches for these boards.

Since there are different bd71847 drivers/dts used on L4.14/L4.19/L5.4, there are

different patches for this issue, please appy the correct patch on the right release branch:

1). imx 4.14.98 2.3.0:

0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch 0002-MLK-23275-2-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-.patch 0003-MLK-23275-3-regulator-bd71837-correct-ldo1-ldo2-grou.patch 2). imx 4.19.35 1.1.0:

0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch 0002-MLK-23275-2-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-.patch 0003-MLK-23846-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-co.patch 3). imx\_5.4.3\_2.0.0:

0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch 0002-MLK-23275-2-ARM64-dts-freescale-imx8mn-ddr4-evk-corr.patch 0003-MLK-23844-1-ARM64-dts-freescale-imx8mn-ddr4-evk-clea.patch 0004-MLK-23844-2-ARM64-dts-freescale-imx8mm-correct-VDDAR.patch

#### Reason

Notice customers not using wrong SW version or download the correct SW version.

#### **Identification of Affected Products**

it is SW error, and No impact to Soc.

## Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

#### **Data Sheet Revision**

No impact to existing datasheet

#### **Contact and Support**

For all inquiries regarding the ePCN tool application or access issues, please <u>contact</u> NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name Mcgregor Amanda

**Position** Marketing

e-mail address mailto:amanda.mcgregor@nxp.com?subject=Support

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

## **About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

NXP Semiconductors High Tech Campus, 5656 AG Eindhoven, The Netherlands © 2006-2010 NXP Semiconductors. All rights reserved.