Errata for FM28V020

RAMTRON

1850 Ramtron Drive Colorado Springs, CO 80921 719-481-7000 FAX: 719-488-9095 www.ramtron.com

Errata Number 001

Date Dec. 10, 2010

Product FM28V020-TG (32-lead TSOP)

The 32-lead TSOP-I package does not have a pin 1 indicator in the corner of the package. The affected devices are marked with the date code 1001 through 1105. This problem has been fixed. The correct package marking with the pin 1 indicator dot will become available as date codes 1106 and higher.

