


# Errata for FM28V100

## RAMTRON


1850 Ramtron Drive  
Colorado Springs, CO 80921  
719-481-7000 FAX: 719-488-9095  
www.ramtron.com

**Errata Number** 002  
**Date** Dec. 10, 2010  
**Product** FM28V100-TG (32-lead TSOP)

The 32-lead TSOP-I package does not have a pin 1 indicator in the corner of the package. The affected devices are marked with the date code 1001 through 1105. This problem has been fixed. The correct package marking with the pin 1 indicator dot will become available as date codes 1106 and higher.



Date Codes 1001 - 1105



Date Codes 1106 and up