12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20151215005
Datasheet for TMP275
Information Only

Date: 12/16/2015
To: TOKYO ELECTRON DEVICE (DSTR) PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20151215005
Information Only
Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
TMP75AIDGKR	null
TMP75AIDR	null
TMP75AIDRG4	null
TMP75AIDGKT	null
TMP75AID	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20151215005	**PCN Date:**	12/16/2015
Title:	Datasheet for TMP175 and TMP75		
Customer Contact:	PCN Manager	**Dept:**	Quality Services
Change Type:			

☐ Assembly Site	☐ Design	☐ Wafer Bump Site
☐ Assembly Process	☒ Data Sheet	☐ Wafer Bump Material
☐ Assembly Materials	☐ Part number change	☐ Wafer Bump Process
☐ Mechanical Specification	☐ Test Site	☐ Wafer Fab Site
☐ Packing/Shipping/Labeling	☐ Test Process	☐ Wafer Fab Materials
		☐ Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification etc.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



TEXAS INSTRUMENTS

TMP175, TMP75

SBOS288L – JANUARY 2004 – REVISED DECEMBER 2015

Changes from Revision K (April 2015) to Revision L	Page
- Changed second Features bullet: added NIST Traceable to TMP75 device	1
- Added last paragraph to *Description* section	1
- Deleted *Simplified Schematic* figure from page 1	1
- Changed the *Timing Requirements* table	6
- Changed Figure 6	13

Device Family	Change From:	Change To:
TMP175 and TMP75	SBOS288K	**SBOS288L**

These changes may be reviewed at the datasheet links provided.
http://www.ti.com/product/TMP75

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TMP175AID	TMP175AIDG4	TMP175AIDGKR	TMP175AIDGKT
TMP175AIDGKTG4	TMP175AIDR	TMP175AIDRG4	TMP75AID
TMP75AIDG4	TMP75AIDGKR	TMP75AIDGKRG4	TMP75AIDGKT
TMP75AIDGKTG4	TMP75AIDR	TMP75AIDRG4	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	**E-Mail**
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com