

PCN: V11-017-48475412-0A

Product Change Notice

Issue Date: 27 Oct 2011

Change Type:

Ammopack Packaging Box Design Change

<u>Parts Affected:</u>
The list of part numbers affected by the change are

The list of part numbers ansocial by the change are				
HLMF-K200#2CA	HLMF-K500#2CA	HLMP-3316-HK0CA	HLMP-C627-P00DD	QLMP-U897-K0CDD
HLMF-K200#2UK	HLMF-K500#2UL	HLMP-3519-GJ0CA	HLMP-DS25-F00DD	QLMP-U899-N0CDD
HLMF-K200#2UL	HLMF-K500#2UM	HLMP-3519-GJ0UT	HLMP-N205-H00DD	QLMP-4003-000DD
HLMF-K200#2UM	HLMF-K500#2UP	HLMP-C008-U00DD	HLMP-N305-G00DD	QLMP-J355-IJGDD
HLMF-K200#2UP	HLMF-K505#2CD	HLMP-C025-P00DD	HLMP-N505-G00DD	QLMP-K229#2MK
HLMF-K205#2CA	HLMF-K505#2UK	HLMP-C208-S00DD	HLMP-NM31-R00DD	QLMP-K556#2MK
HLMF-K205#2UN	HLMF-KG02#2CA	HLMP-C208-SVGDD	HLMP-NS30-J00DD	
HLMF-K300#2CA	HLMF-KG02-OP0CA	HLMP-C225-O00DD	HLMP-NS30-MP0DD	
HLMF-K300#2UK	HLMP-3301-F00DD	HLMP-C610-R00DD	QLMJ-A017-F00UT	
HLMF-K400#2UL	HLMP-3301-FI0UK	HLMP-C610-VX0DD	QLMP-NS33-J00DD	

Description and Extent of Change:


The above part numbers will be packed using new ammopack box design.

Reasons for Change:


To prevent wrong orientation during device loading and unloading from ammopack box.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The change is limited to packaging box only, no change on the product and box dimension. Below is the design of new ammopack box.



Your Imagination, Our Innovation



Effective Date of Change:

Shipment with new ammopack box will be effective from 1st Dec 2011 onward. There will be a combination of old and new ammopack box design in one shipment during transition period until the old ammopack boxes depleted.

Qualification Data:

Not Applicable.

These changes have been reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Avago Technologies field sales engineer or Contact Center (http://www.avagotech.com/contact/) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.