

Product Change Notification		Date July 9, 2021
Product	ConnectCore 6 SOM/SBC/KIT(Limited P/N) and ConnecCore 6+ SOM/SBC/KIT(Limited P/N)	

Reason for Change

Technical Requirement	Product Transition
Customer Requirement	Product Discontinuation
Quality Improvement	Product Enhancement
	Other (Brand Change)

Description of change	The SOM and SBC part numbers listed under affected part numbers below were populated with an additional Cortex-M microcontroller. The microcontroller does not contain any Digi firmware and is not a requirement for the SOMs or SBCs to function. The intent was to provide an option to host customer application code. The microcontroller has sourcing issues and would have an adverse effect on pricing. Going forward Digi will not populate this microcontroller anymore. There is no change in the functionality of the product.
------------------------------	--

Affected Part Numbers-/Timing	See attachment
--------------------------------------	----------------

Quality Issues	None
-----------------------	------

Contact/Questions	Please contact your Digi Sales Representative or Technical Support team via email at tech.support@digi.com .
--------------------------	---

Issued By	Digi International Embedded Product Management
------------------	--

Part number	Description	New Revision level *See attachment for location	Timing
CC-WMX-J97C-TN	ConnectCore 6 QD 1GHz 4GF 1GR W/B MA	J	3rdQtr 2021
CC-SB-WMX-J97C	ConnectCore Wi-i.MX6 Quad,1.2GHz,0-70C,BT	F	3rdQtr 2021
CC-WMX-KK8D-TN	CC i.MX6QP 8GB FL/2GB QC 1GHz, -40-+85	E	3rdQtr 2021
CC-SB-WMX-KK8D	ConnectCore 6 QP SBC 1GHz 8GF 2GR	D	3rdQtr 2021

	W/B		
CC-WMX6-KIT	ConnectCore Wi-i.MX6 JSK	M	3rdQtr 2021
CC-WMX6P-KIT	ConnectCore Wi-i.MX6 Plus Kit	F	3rdQtr 2021

IGI **ConnectCore 6**
 I-Q-8-1-WiFi-BT
 P/N:(1P)CC-WMX-L97D-RV
 S/N:(S) U101????? ?
 CoO: ???

U/C/E 5
 6 63072 96030 3
 96015964C
 2101
 CE
 digi.com

Rev level