

**DATE:**

May 2, 2016

**PRODUCT:**

ConnectCore for i.MX51  
ConnectCore for i.MX53

**REASON:**

Three-axis accelerometer component obsolescence

**PART NUMBERS AFFECTED (SKUs):**

All active ConnectCore for i.MX51 and ConnectCore for i.MX53 SKUs

**ESTIMATED EFFECTIVITY:**

September 1, 2016

**NOTICE:**

Due to component obsolescence, the Freescale/NXP Accelerometer component MMA7455L will no longer be available as a standard population on all active ConnectCore for i.MX51/i.MX53 SKUs.

The component (and the functionality it provides) will be removed from the ConnectCore for i.MX51/i.MX53 product line, per the effectivity date stated above.

If you have any additional questions or concerns, please contact your local Digi channel partner or Digi account manager.

---

**MIKE ROHRMOSER**

DIRECTOR OF PRODUCT MANAGEMENT, EMBEDDED SYSTEMS



11001 Bren Road East, Minnetonka, MN 55343