



Product Change Notification

Change Notification #: 114501 - 00

Change Title: Intel® SSD DC S3610 Series (200GB, 400GB, 800GB, 1.8in SATA 6Gb/s, 20nm, MLC) 7mm, Generic Single Pack, Intel® SSD DC S3610 Series (200GB, 400GB, 800GB, 1.8in SATA 6Gb/s, 20nm, MLC) 7mm, Generic 50 Pack, Intel® SSD DC S3610 Series (100GB, 200GB, 400GB, 480GB, 800GB, 1.2TB, 1.6TB, 2.5in SATA 6Gb/s, 20nm, MLC) 7mm, Generic Single Pack, Intel® SSD DC S3610 Series (100GB, 200GB, 400GB, 480GB, 800GB, 1.2TB, 1.6TB, 2.5in SATA 6Gb/s, 20nm, MLC) 7mm, Generic 50 Pack, Intel® SSD DC S3710 Series (200GB, 400GB, 800GB, 1.2TB, 2.5in SATA 6Gb/s, 20nm, MLC) 7mm, Generic Single Pack, Intel® SSD DC S3710 Series (200GB, 400GB, 800GB, 1.2TB, 2.5in SATA 6Gb/s, 20nm, MLC) 7mm, Generic 50 Pack, PCN 114501-00, Product Design, Firmware Update

Date of Publication: March 30, 2016

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 30, 2016
---	--------------

Description of Change to the Customer:

The Intel® SSD DC S3610 Series and Intel® SSD DC S3710 Series firmware version is being updated from G2010140 to G2010150. The changes in the new firmware version are incremental improvements from previous version. Inventory will transition in the Intel factory on or beyond the above date to replace older firmware version with the latest version. Customers should be ready to receive the post-conversion material any time after May 30, 2016.

Customer Impact of Change and Recommended Action:

Since the firmware update has incremental improvement over the previous version, Intel anticipates no product impact with this firmware, and re-qualification is not recommended.

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

Milestone dates are estimates and subject to change based on business and operational conditions.

Please contact your local Intel Field Sales Representative if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Pre Change SA	Post Change TA	Post Change SA
SSDSC2BA200G401	937741	H51472-301	H51455-301	H51472-302	H51455-302
SSDSC2BA200G4	937742	H51473-301	H51455-301	H51473-302	H51455-302
SSDSC2BA400G401	937743	H51476-301	H51475-301	H51476-302	H51475-302
SSDSC2BA400G4	937744	H51478-301	H51475-301	H51478-302	H51475-302
SSDSC2BA800G401	937745	H51482-301	H51479-301	H51482-302	H51479-302
SSDSC2BA800G4	937746	H51483-301	H51479-301	H51483-302	H51479-302
SSDSC2BA012T401	937747	H51486-301	H51485-301	H51486-302	H51485-302
SSDSC2BA012T4	937748	H51487-301	H51485-301	H51487-302	H51485-302
SSDSC1BG200G401	939145	H66016-101	H66017-101	H66016-102	H66017-102
SSDSC1BG200G4	939146	H66018-101	H66017-101	H66018-102	H66017-102
SSDSC1BG400G401	939147	H66019-101	H66020-101	H66019-102	H66020-102
SSDSC1BG400G4	939148	H66021-101	H66020-101	H66021-102	H66020-102
SSDSC1BG800G401	939149	H66022-101	H66023-101	H66022-102	H66023-102
SSDSC1BG800G4	939150	H66024-101	H66023-101	H66024-102	H66023-102
SSDSC2BX200G4	940778	H63922-301	H63921-301	H63922-302	H63921-302
SSDSC2BX200G401	940779	H63920-301	H63921-301	H63920-302	H63921-302
SSDSC2BX400G4	940780	H63925-301	H63924-301	H63925-302	H63924-302
SSDSC2BX400G401	940781	H63923-301	H63924-301	H63923-302	H63924-302
SSDSC2BX480G4	940782	H63927-301	H63928-301	H63927-302	H63928-302
SSDSC2BX480G401	940783	H63926-301	H63928-301	H63926-302	H63928-302
SSDSC2BX800G4	940784	H63931-301	H63930-301	H63931-302	H63930-302
SSDSC2BX800G401	940785	H63929-301	H63930-301	H63929-302	H63930-302
SSDSC2BX012T4	940786	H63934-301	H63933-301	H63934-302	H63933-302
SSDSC2BX012T401	940788	H63932-301	H63933-301	H63932-302	H63933-302
SSDSC2BX016T4	940789	H63938-301	H63937-301	H63938-302	H63937-302
SSDSC2BX016T401	940790	H63936-301	H63937-301	H63936-302	H63937-302
SSDSC2BX100G401	942238	H71291-301	H71292-301	H71291-302	H71292-302
SSDSC2BX100G4	942239	H71293-301	H71292-301	H71293-302	H71292-302

PCN Revision History:

Date of Revision:

March 30, 2016

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

114501 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.