



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN# 20150310003A
Withdrawal of Select PDIP Products
Product Withdrawal/Discontinuance Notification

Dear Customer:

The purpose of revision A is to correct some recommended replacement part numbers. We apologize for any inconvenience this may have created.

This is an announcement of the impending withdrawal of a device(s) that is currently offered by Texas Instruments.

This product withdrawal will be offering a life time buy on the affected products. Recommended replacement(s) are listed in the Product Affected Section of this notification when applicable. The details are in the following pages.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

PCN# 20150310003A
Attachment: 1

Products Affected:

According to our records, there are the affected device(s) that you have purchased within the past twenty-four (24) months. Technical details of this Product Change follow on the next page(s).

PCN Number:	PCN20150310003A		PCN Date:	04/22/2015
Title:	Withdrawal of Select PDIP Products			
Customer Contact:	PCN Manager	Dept:	Quality Services	
Last date to order:	03/12/2016	Last date to ship:	06/12/2016	
Change Type:	Product Withdrawal - End Of Life			
Product Withdrawal/Discontinuance Notification Details				
Description of Withdrawal/Discontinuance:				
<p>The purpose of revision A is to correct some recommended replacement part numbers that were listed in error. These corrections are highlighted in yellow in the Product Affected Section of this document.</p> <p>Texas Instruments, Incorporated (TI) is announcing the withdrawal of select PDIP Products. A lifetime buy is offered on all devices. Recommended replacements are being offered on some devices as shown in the Product Affected Section.</p>				
Reason for Withdrawal/Discontinuance:				
These products can no longer be manufactured at the current location and will not be qualified at any other site.				
Product Affected:				
Parts Being Obsolesced	RECOMMENED REPLACEMENT PRODUCTS	REPLACEMENT CODES	Device Pin Count	
TPS23851DCE	TPS23861PWR	P	36	
TPS23851DCER	TPS23861PWR	P	36	
UCC5630AMWPTR	No replacement part available	Not Applicable	36	
UCC5630AMWPTRG4	No replacement part available	Not Applicable	36	
UC2524N	UC2524DW	S	16	
UC2524NG4	UC2524DW	S	16	
UC2543N	UC2543J	S	16	
UC2543NG4	UC2543J	S	16	
UC2572N	No replacement part available	Not Applicable	8	
UC2573N	No replacement part available	Not Applicable	8	
UC2573NG4	No replacement part available	Not Applicable	8	
UC2578N	No replacement part available	Not Applicable	16	
UC2578NG4	No replacement part available	Not Applicable	16	
UC27131N	UC27131D	S	8	
UC2714N	UC2714D	S	8	
UC2715N	UC2715D	S	8	
UC2715NG4	UC2715D	S	8	
UC28023N	UC28023DW	S	16	
UC2833N	UC2833DW	S	8	
UC2834N	UC2834J	S	16	
UC2835N	UC2835D	S	8	
UC2847N	UC2847DW	S	16	
UC2853AN	UC2853AD	S	8	
UC2853AN-P	UC2853AD	S	8	

UC2863N	UCC2863DW UC2863DW	S	16
UC2865N	UCC28950 UCC28950PW	F	16
UC2866N	UCC28950PW	S	16
UC2866NG4	UCC28950PW	S	16
UC2872N	No replacement part available	Not Applicable	14
UC2872NG4	No replacement part available	Not Applicable	14
UC3524N	UC3524D	S	16
UC3527BN	UC3527AN	F	16
UC3527BNG4	UC3527ANG4	F	16
UC3543N	UC3543J	S	16
UC3543NG4	UC3543J	S	16
UC3572N	No replacement part available	Not Applicable	8
UC3573N	No replacement part available	Not Applicable	8
UC3573NG4	No replacement part available	Not Applicable	8
UC3578N	No replacement part available	Not Applicable	16
UC37132N	UC37132D	S	14
UC37133N	UC27133D	S	8
UC3714N	UC2714D	S	8
UC3715N	UC2715D	S	8
UC3715NG4	UC2715D	S	8
UC3823BN	UC3823BDW	S	16
UC3832N	UC3832DW	S	14
UC3832NG4	UC3832DWG4	S	14
UC3833N	UC2833DW	P	8
UC3833NG4	UC2833DWG4	S	8
UC3834N	UC3834DW	S	16
UC3834NG4	UC3834DWG4	S	16
UC3835N	UC2835D	P	8
UC3836N	UC3836D	S	8
UC3836NG4	UC3836DG4	S	8
UC3847N	UC3847DW	S	16
UC3854N-F	UC3854DW	S	16
UC3862N	UCC28950PWR	F	16
UC3863N	UC2863DW	S	16
UC3864N	UC3864DW UC2864DW	S	16
UC3865N	UC3865DW	S	16
UC3865NG4	UC3865DW	S	16
UC3868N	UCC28950PW	F	16
UC3872N	No replacement part available	Not Applicable	14
UC3872NG4	No replacement part available	Not Applicable	14
UC39431N	UC39431D	S	8
UC39432BN	UCC39432BD UC39432BD	S	8
UC39432BNG4	UC39432BDG4	S	8
UCC2580N-1	UCC2897APW	F	16

UCC2580N-1G4	UCC2897APW	F	16
UCC2580N-2	UCC2897APW	F	16
UCC2580N-2G4	UCC2897APW	F	16
UCC2580N-3	UCC2580D-3	S	16
UCC2580N-3G4	UCC2580D-3G4	S	16
UCC2580N-4	UCC2897APW	F	16
UCC2580N-4G4	UCC2897APW	F	16
UCC2583N	UCC2583D	S	14
UCC2583NG4	UCC2583DG4	S	14
UCC2819N	UCC2818AD	S	16
UCC3580N-1	UCC2580D-3	S	16
UCC3580N-1G4	UCC2580D-3G4	S	16
UCC3580N-2	UCC2897APW	F	16
UCC3580N-2G4	UCC2897APW	F	16
UCC3580N-3	UCC2897APW	F	16
UCC3580N-3G4	UCC2897APW	F	16
UCC3580N-4	UCC2897APW	F	16
UCC3580N-4G4	UCC2897APW	F	16
UCC3581N	UCC3581D UCC3581D	S	14
UCC3583N	UCC3583D	S	14
UCC3583NG4	UCC3583D	S	14
UCC3585N	No replacement part available	Not Applicable	16
UCC3819N	UCC3818AD	F	16
UCC3884N	UCC3884D	S	16
UCC3884NG4	UCC3884D	S	16
UCC3972N	No replacement part available	Not Applicable	8
UCC81511N	Custom Device	Not Applicable	16

Replacement Notes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com