



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PTN# 20150901004
Withdrawal of the Select Devices Sourced in GFAB6
Product Withdrawal/Discontinuance Notification

Dear Customer:

Because you have purchased one or more of the products listed on the attachment during the past twenty-four (24) months, we would like to know if you have any continuing requirements for them in the future. We would appreciate your advising us of any such requirements and estimated quantities needed as soon as possible.

In an attempt to satisfy any continuing requirements you may have, TI is offering a non-cancelable lifetime buy for the product. Related dates are included on the attachment. We will contact you as soon as we have completed our review of all customer responses to determine the appropriate course of action required to satisfy your needs for this/these products.

This notification period is per TI's standard process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

If you require additional supply beyond the dates defined in this letter, please contact your local Field Sales Representative to determine if the parts may be available from a TI-authorized distributor for discontinued products. There is no guarantee of continued supply for these products.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

PCN # 20150901004
Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months.

For this PCN, in addition to listing the TI PCN Affected Device and the customer part # (if available) in the table below, we are also including a suggested 'Replacement' Device (if available) and the Replacement 'Code' as follows:

Replacement Code Key:

- F = Similar functionality but not equivalent.
- P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.
- Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.
- S = EXACT equivalent in functionality and parametrically to the compared device.

Affected Device	Replacement Device	Code
ADC0803LCN	ADC0803LCN/NOPB	S
DAC0800LCN	DAC0800LCN/NOPB	S
DS14C232CM/NOPB	MAX3232ECDR	Q
DS14C232CMX/NOPB	MAX3232ECDR	Q
DS14C232CN/NOPB	MAX3232ECDR	P
DS14C232TM/NOPB	MAX3232EIDR	Q
DS14C232TMX/NOPB	MAX3232EIDR	Q
DS14C238WMX/NOPB	MAX208CDWR	Q
DS14C335MSA/NOPB	SN75LV4737ADBR	P
DS14C335MSAX/NOPB	SN75LV4737ADBR	P
DS14C535MSAX/NOPB	SN75LV4737ADBR	P
DS26LS31CMX	DS26LS31CMX/NOPB	S
DS26LS31CMX/NAK1	DS26LS31CMX/NOPB	S
DS26LS32ACMX	DS26LS32ACMX/NOPB	S
DS26LS32ACMX/NAK1	DS26LS32ACMX/NOPB	S
DS26LS32ACN	DS26LS32ACMX/NOPB	P
DS26LS32ACN/NOPB	DS26LS32ACMX/NOPB	P
DS26LS32CN/NOPB	DS26LS32CMX/NOPB	P
DS3487M/NOPB	DS3487MX/NOPB	Q
DS8923AM	DS8923AM/NOPB	S
DS96174CN/NOPB	SN75LBC174AN	Q
DS96175CN/NOPB	SN75LBC175AN	Q
DS96176CN/NOPB	SN75LBC176AP	Q
LHV720MA/NOPB	LM4562MAX/NOPB	F
LHV720MAX/NOPB	LM4562MAX/NOPB	F
LM1036M/NOPB	None	None
LM1851MX/NOPB	None	None
LM185BXH-2.5	LM285LP-2-5	F
LM1876T/NOPB	LM4766T/NOPB	F
LM1876TF/NOPB	LM4766T/NOPB	F
LM1877M-9/NOPB	LM386MX-1/NOPB	F

LM1877MX-9/NOPB	LM386MX-1/NOPB	F
LM1894MX/NOPB	TLV320AIC3256	F
LM2577S-12/NOPB	LM2585S-12/NOPB	Q
LM2577SX-12/NOPB	LM2585SX-12/NOPB	Q
LM2577T-12/NOPB	LM2585T-12/NOPB	Q
LM2577T-15/NOPB	LM2585T-ADJ/NOPB	F
LM2641MTCX-ADJ/NOPB	None	None
LM2695MHX/NOPB	None	None
LM2936Z-3.0/NOPB	LM2936MPX-3.0/NOPB	P
LM3430SD/NOPB	LM5121MH/NOPB	F
LM3432MH/NOPB	TPS61196PWPT	F
LM3432MHX/NOPB	TPS61196PWPR	F
LM3432SQ/NOPB	TPS61196PWPT	F
LM380N/NOPB	LM4954TL/NOPB	F
LM380N-8/NOPB	LM4954TL/NOPB	F
LM386M-1/NOPB	LM386MX-1/NOPB	Q
LM386N-1/NOPB	LM386MX-1/NOPB	Q
LM386N-3/NOPB	LM386MX-1/NOPB	Q
LM386N-4/NOPB	LM386MX-1/NOPB	Q
LM3875TF/NOPB	None	None
LM3876T/NOPB	None	None
LM3876TF/NOPB	None	None
LM3915N-1/NOPB	LP3943, LP3944	F
LM3916N-1/NOPB	LP3943, LP3944	F
LM4562NA/NOPB	LM4562MAX/NOPB	Q
LM4702CTA/NOPB	None	None
LM4752TS/NOPB	TPA3110D2	F
LM4755TS/NOPB	TPA3110D2	F
LM4755TSX/NOPB	TPA3110D2	F
LM4765T/NOPB	LM4766T/NOPB	F
LM4766TF/NOPB	LM4766T/NOPB	Q
LM4960SQ/NOPB	LM48560TL/NOPB	F
LM4961LQ/NOPB	LM48560TL/NOPB	F
LM5072MH-50/NOPB	TPS23756	F
LM5072MHX-50/NOPB	TPS23756	F
LM5073MH/NOPB	TPS2376DDA-H	P
LM5073MHX/NOPB	TPS2376DDA-H	P
LM5080MM/NOPB	UCC29002	P
LM5100MX/NOPB	LM5100AMX/NOPB	P
LM833M/NOPB	LM833MX/NOPB	Q
LM833MX	LM833MX/NOPB	Q
LM833N/NOPB	LM833MM/NOPB	Q
LM837M/NOPB	None	None
LM837MX/NOPB	None	None
LMC567CM/NOPB	LMC567CMX/NOPB	Q
LMC567CMX/NAK2	LMC567CMX/NOPB	Q
LMC567CN/NOPB	LMC567CMX/NOPB	Q
LME49600TS/NOPB	None	None
LME49610TS/NOPB	None	None
LME49710MA/NOPB	None	None
LME49710MAX/NOPB	None	None
LME49710NA/NOPB	None	None
LME49713MA/NOPB	None	None
LME49720MA/NOPB	LME49720MAX/NOPB	Q
LME49720NA/NOPB	LME49720MAX/NOPB	Q
LME49722MA/NOPB	None	None
LME49723MA/NOPB	LME49723MAX/NOPB	Q
LME49724MR/NOPB	LME49724MRX/NOPB	Q
LME49740MA/NOPB	None	None
LME49860MA/NOPB	None	None

LME49860NA/NOPB	None	None
LME49880MR/NOPB	LME49860MAX/NOPB	Q
LME49990MA/NOPB	None	None
LME49990MAX/NOPB	None	None
LMF100CIWM/NOPB	None	None
LMF100CIWMX/NOPB	None	None
LP2952AIM-3.3/NOPB	LP2953AIMX/NOPB	F
LP2954ISX/AULF	LP2957AIT/NOPB	P
LP2957IS/NOPB	LP2957AIT/NOPB	F
LP2960AIM-3.3/NOPB	LP2960IMX-3.3/NOPB	S
LP2960AIM-5.0/NOPB	LP2960AIMX-5.0/NOPB	S
LP2960IM-3.3/NOPB	LP2960IMX-3.3/NOPB	Q
LP2975AIMM-5.0/NOPB	None	None
LP2975IMM-3.3/NOPB	None	None
LP2975IMM-5.0/NOPB	None	None
LP2985AITL-1.8/NOPB	LP2985AIM5-1.8/NOPB	S
LP2985AITP-1.8/NOPB	LP2985AIM5-1.8/NOPB	S
LP2985AITP-3.3/NOPB	LP2985AIM5-3.3/NOPB	S
LP2985AITP-5.0/NOPB	LP2985AIM5-5.0/NOPB	S
LP2985AITPX-5.0/NOPB	LP2985AIM5X-5.0/NOPB	S

Technical details of this Product Change follow on the next page(s).

PTN Number:	20150901004			PTN Date:	09/28/2015
Title:	Withdrawal of Select Devices Sourced in GFAB6				
Customer Contact:	PCN Manager			Dept:	Quality Services
Last date to order:	09/28/2016		Last date to ship:	03/28/2017	
Change Type:	Product Withdrawal - End Of Life				
Product Withdrawal / Discontinuance Notification Details					
Description of Withdrawal / Discontinuance:					
Texas Instruments, Incorporated (TI) is announcing the withdrawal of select devices sourced in GFAB6. A lifetime buy is being offered with the date given above. Recommended replacements are being offered on most devices as shown in page 2 of this document.					
Reason for Withdrawal / Discontinuance:					
Manufacturing support for the 6 inch line is discontinuing.					
Product Affected:					
Please see affected device list on page 2.					

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com