



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

**Notification# 20160715000
Datasheet for LM4132/ LM4132-Q1
Information Only Datasheet**

Date: 7/20/2016
To: TOKYO ELECTRON DEVICE (DSTR) PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20160715000
Information Only Datasheet
Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
LM4132CMF-2.5/NOPB	null
LM4132AMF-4.1/NOPB	null
LM4132AMFX-3.3/NOPB	null

Technical details of this Product Change follow on the next page(s).

Notification Number:	20160715000	Notification Date:	07/20/2016
Title:	Datasheet for LM4132/ LM4132-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
☐ Assembly Site	☐ Design	☐ Wafer Bump Site	
☐ Assembly Process	☒ Data Sheet	☐ Wafer Bump Material	
☐ Assembly Materials	☐ Part number change	☐ Wafer Bump Process	
☐ Mechanical Specification	☐ Test Site	☐ Wafer Fab Site	
☐ Packing/Shipping/Labeling	☐ Test Process	☐ Wafer Fab Materials	
		☐ Wafer Fab Process	

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification.
The product datasheet(s) is updated as seen in the change revision history below:



LM4132, LM4132-Q1

SNVS372F – AUGUST 2005 – REVISED MARCH 2016

www.ti.com

Changes from Revision E (January 2016) to Revision F

Page

- Added correct *Layout Example* 25

The following change history provides further details

The datasheet number will be changing.

Device Family	Change From:	Change To:
LM4132/LM4132-Q1	SNVS372E	SNVS372F

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/lit/ds/symlink/lm4132-q1.pdf>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device

Changes to product identification resulting from this notification:

None.

Product Affected:

LM4132AMF-1.8/NOPB	LM4132BMF-3.0/NOPB	LM4132CMF-4.1/NOPB	LM4132DMFX-3.0/NOPB	
LM4132AMF-2.0/NOPB	LM4132BMF-3.3/NOPB	LM4132CMFX-1.8/NOPB	LM4132DMFX-3.3/NOPB	
LM4132AMF-2.5/NOPB	LM4132BMF-4.1	LM4132CMFX-2.0/NOPB	LM4132DMFX-4.1/NOPB	
LM4132AMF-3.0/NOPB	LM4132BMF-4.1/NOPB	LM4132CMFX-2.5/NOPB	LM4132DQ1MFR2.5	
LM4132AMF-3.3/NOPB	LM4132BMFX-1.8/NOPB	LM4132CMFX-3.0/NOPB	LM4132DQ1MFR3.0	
LM4132AMF-4.1	LM4132BMFX-2.0/NOPB	LM4132CMFX-3.3/NOPB	LM4132DQ1MFT2.5	
LM4132AMF-4.1/NOPB	LM4132BMFX-2.5/NOPB	LM4132CMFX-4.1/NOPB	LM4132DQ1MFT3.0	
LM4132AMFX-1.8/NOPB	LM4132BMFX-3.0/NOPB	LM4132CQ1MFR2.5	LM4132EMF-1.8/NOPB	
LM4132AMFX-2.0/NOPB	LM4132BMFX-3.3/NOPB	LM4132CQ1MFR3.0	LM4132EMF-2.0/NOPB	
LM4132AMFX-2.5/NOPB	LM4132BMFX-4.1/NOPB	LM4132CQ1MFT2.5	LM4132EMF-2.5/NOPB	
LM4132AMFX-3.0/NOPB	LM4132BQ1MFR2.5	LM4132CQ1MFT3.0	LM4132EMF-3.0/NOPB	

LM4132AMFX-3.3/NOPB	LM4132BQ1MFR3.0	LM4132DMF-1.8/NOPB	LM4132EMF-3.3/NOPB	
LM4132AMFX-4.1/NOPB	LM4132BQ1MFT2.5	LM4132DMF-2.0/NOPB	LM4132EMF-4.1/NOPB	
LM4132AQ1MFR2.5	LM4132BQ1MFT3.0	LM4132DMF-2.5/NOPB	LM4132EMFX-1.8/NOPB	
LM4132AQ1MFR3.0	LM4132CMF-1.8/NOPB	LM4132DMF-3.0/NOPB	LM4132EMFX-2.0/NOPB	
LM4132AQ1MFT2.5	LM4132CMF-2.0/NOPB	LM4132DMF-3.3/NOPB	LM4132EMFX-2.5/NOPB	
LM4132AQ1MFT3.0	LM4132CMF-2.5/NOPB	LM4132DMF-4.1/NOPB	LM4132EMFX-3.0/NOPB	
LM4132BMF-1.8/NOPB	LM4132CMF-3.0/NOPB	LM4132DMFX-1.8/NOPB	LM4132EMFX-3.3/NOPB	
LM4132BMF-2.0/NOPB	LM4132CMF-3.3/NOPB	LM4132DMFX-2.0/NOPB	LM4132EMFX-4.1/NOPB	
LM4132BMF-2.5/NOPB	LM4132CMF-4.1	LM4132DMFX-2.5/NOPB		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com