



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PDN# 20171205004
Discontinuance of TMP006 and TMP007 Family of Devices
Product Discontinuance Notification

Date: December 06, 2017
To: TOKYO ELECTRON DEVICE (DSTR) PCN

Dear Customer:

The recipient has been identified for notification of changes for one or more of the products affected by the change detailed in the notice. Customers are notified based on the past twenty-four (24) months of the customer's purchase history or the recipient is listed as being part of GIDEP (Government-Industry Data Exchange Program).

Any inquiries should be directed to your local Field Sales Representative.

If you require additional supply, please contact your local Field Sales Representative to determine if the parts may be available from a TI-authorized distributor for discontinued products. There is no guarantee of continued supply for these products.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20171205004
Attachments1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
TMP007AIYZFR	null
TMP006AIYZFR	null
TMP006AIYZFT	null

Details of this Product Discontinuance follow on the next page(s).

PDN Number:	20171205004	PDN Date:	Dec 6, 2017
Title:	Discontinuance of TMP006 and TMP007 Family of Devices		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:	Product Discontinuance - End Of Life		
Product Discontinuance Notification Details			
Description of Discontinuance:			
<p>Texas Instruments Incorporated (TI) is announcing the discontinuance of the TMP006 and TMP007 family of devices. A life time buy is not being offered, nor does TI have any products that could serve as suitable replacement devices.</p> <p>NOTE: There are no samples offered for withdrawn/obsolete products. If you have any questions, please contact your local sales representative.</p>			
Reason for Discontinuance:			
This device requires a unique process flow which has been obsoleted in all TI factories.			
Product Affected:			
Product Being Discontinued	RECOMMENDED REPLACEMENT PRODUCTS	REPLACEMENT CODES	
HPA01108AIYZFR	None	Not Applicable	
TMP006AIYZFR	None	Not Applicable	
TMP006AIYZFT	None	Not Applicable	
TMP006BIYZFR	None	Not Applicable	
TMP006BIYZFT	None	Not Applicable	
TMP007AIYZFR	None	Not Applicable	
TMP007AIYZFT	None	Not Applicable	
Replacement Notes:			
<p>F = Similar functionality but not equivalent.</p> <p>P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.</p> <p>Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.</p> <p>S = EXACT equivalent in functionality and parametrically to the compared device.</p>			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com