

PCN: V11-018-48475412-0A

Product Change Notice

Issue Date: 4th Nov 2011

Change Type:

Alternate manufacturing site for the parts listed below.

Parts Affected:

The list of part numbers affected by the change are:

HLMF-K200	HLMP-K105	HLMP-1600	HLMP-3519-GJ0UT	QLMP-D143
HLMF-K200#2CA	HLMP-K105-J0002	HLMP-1600-D00A1	HLMP-3750	QLMP-D272-J0000
HLMF-K200#2UK	HLMP-K150	HLMP-1600-D00A2	HLMP-3750-L0002	QLMP-D578
HLMF-K200#2UL	HLMP-K150-C0002	HLMP-1601	HLMP-3750-L00B2	QLMP-DS49-E0000
HLMF-K200#2UM	HLMP-K150-C00A1	HLMP-1620	HLMP-3762	QLMP-G243-L0000
HLMF-K200#2UP	HLMP-K150-CD000	HLMP-1620-C00A1	HLMP-3762-G00B2	QLMP-G540
HLMF-K205#2CA	HLMP-K150-CD002	HLMP-1620-C00A2	HLMP-3850	QLMP-G543-K0000
HLMF-K205#2UN	HLMP-K155	HLMP-1621	HLMP-3850-K0002	QLMP-U897-K0CDD
HLMF-K300#2CA	HLMP-K155-D0002	HLMP-1640	HLMP-3850-K00B2	QLMP-U899-N0000
HLMF-K300#2UK	HLMP-K401-EF000	HLMP-1640-B00A1	HLMP-3914	QLMP-U899-N0CDD
HLMF-K400#2UL	HLMP-KA45-E0000	HLMP-1640-B00A2	HLMP-3950	HLMP-3351
HLMF-K405	HLMP-KA45-J0000	HLMP-1640-DE000	HLMP-3950-K0001	HLMP-3351-D0000
HLMF-K500#2CA	HLMP-KA45-NQ000	HLMP-1641	HLMP-3950-K0002	HLMP-3351-D0002
HLMF-K500#2UL	HLMP-KB45-A0000	HLMP-3595	HLMP-3950-K00B2	HLMP-3351-F00R1
HLMF-K500#2UM	HLMP-N205-H00DD	HLMP-K600	HLMP-3960	HLMP-3366
HLMF-K500#2UP	HLMP-N305-G00DD	HLMP-R100	HLMP-3960-K0002	HLMP-3390
HLMF-K505	HLMP-N505-G00DD	HLMP-S100	HLMP-3962	HLMP-3451
HLMF-K505#2CD	HLMP-NG05	HLMP-S201	HLMP-3962-F0002	HLMP-3451-D0000
HLMF-K505#2UK	HLMP-NG07	HLMP-S201-D0000	HLMP-3962-F00B2	HLMP-3490
HLMF-KG02	HLMP-NG07-L0002	HLMP-S201-D0002	HLMP-4101	HLMP-3495
HLMF-KG02#2CA	HLMP-NG07-MQ000	HLMP-S301	HLMP-4700	HLMP-3554
HLMF-KG02-OP0CA	HLMP-NL06	HLMP-S301-B0000	HLMP-4700-C0002	HLMP-3554-E0002
HLMF-KL05	HLMP-NL06#002	HLMP-S301-C0000	HLMP-4700-C00B2	HLMP-3554-E00R1
HLMP-1301	HLMP-NM31-R0000	HLMP-S400	HLMP-4700-CD0FH	HLMP-3568
HLMP-1301-E0002	HLMP-NM31-R00DD	HLMP-S401	HLMP-4719	HLMP-3590
HLMP-1301-E00A1	HLMP-NS30-J0000	HLMP-S501	HLMP-4719-A0002	HLMP-3600
HLMP-1301-E00A2	HLMP-NS30-J00DD	HLMP-S501-C0000	HLMP-4719-A00B2	HLMP-3600-D00B2
HLMP-1301-G0002	HLMP-NS30-MP0DD	HLMP-S501-D0002	HLMP-4740	HLMP-3601
HLMP-1301-G00A1	HLMP-NS30-NQ000	QLMP-1576	HLMP-4740-A0002	HLMP-3650
HLMP-1301-GH002	HLMP-Y301-F0000	QLMP-1627	HLMP-4740-A00B1	HLMP-3650-C00B2

HLMP-1321	HLMP-Y402-G0000	QLMP-1642-EFD00	HLMP-4740-A00B2	HLMP-3651
HLMP-1321-G0002	HLMP-Y502-F0000	QLMP-J283-GH0TB	HLMP-C008-U0000	HLMP-3680
HLMP-1340-J0002	HLMP-Y601-J0000	QLMP-J345-IJ0TB	HLMP-C008-U00DD	HLMP-3680-B00B2
HLMP-1401-D0002	HLMP-Y651-G0000	QLMP-J355-IJGDD	HLMP-C025-P0000	HLMP-3681-B0000
HLMP-1401-D00A1	HLMP-Y701-G0000	QLMP-J359	HLMP-C025-P00DD	HLMP-3707-L0002
HLMP-1401-D00A2	HLMP-Y801-JPP00	QLMP-K124	HLMP-C027-P0000	HLMP-3862
HLMP-1401-EF000	HLMP-Y802-F0000	QLMP-K130-JK000	HLMP-C027-P0002	HLMP-3907-K0002
HLMP-1421	HLMP-Y802-JMB00	QLMP-K204	HLMP-C208-S0000	HLMP-3950-LM000
HLMP-1421-F0002	HLMP-Y901-J0000	QLMP-K206-HH0ED	HLMP-C208-S00DD	HLMP-4000
HLMP-1421-F00A2	HLMP-Y902-J0000	QLMP-K229#2MK	HLMP-C208-SVGDD	HLMP-4000#002
HLMP-1440	HLMP-Y951-K0000	QLMP-K270	HLMP-C225-O0000	HLMP-4000#010
HLMP-1440-H0002	QLMP-1467-I0000	QLMP-K353	HLMP-C225-O00DD	HLMP-4015
HLMP-1440-H00A2	QLMP-1472-EFB02	QLMP-K503	HLMP-C608-R0000	HLMP-4719-BCB00
HLMP-1440-HJ000	QLMP-1705	QLMP-K556#2MK	HLMP-C610-R0000	HLMP-C115
HLMP-1440-IJB00	QLMP-1794#SRA	HLMP-3301	HLMP-C610-R00DD	HLMP-C123-L0002
HLMP-1503	QLMP-J352-EFB00	HLMP-3301-D0000	HLMP-C610-VX0DD	HLMP-C215
HLMP-1503-C0002	QLMP-K285-G00FA	HLMP-3301-D0001	HLMP-C625-P0000	HLMP-C223
HLMP-1503-C00A1	QLMP-K358-H00FA	HLMP-3301-D0002	HLMP-C625-P0002	HLMP-C315
HLMP-1503-C00A2	QLMP-K367	HLMP-3301-D00B2	HLMP-C627-P00DD	HLMP-C323
HLMP-1503-D0002	QLMP-K479	HLMP-3301-F0001	HLMP-D101	HLMP-C415
HLMP-1503-DE000	QLMP-K506-EE0ED	HLMP-3301-F0002	HLMP-D101-J0002	HLMP-C423
HLMP-1503-E0000	QLMP-KB50-B0000	HLMP-3301-F00B2	HLMP-D101-JK000	HLMP-C423-L0002
HLMP-1521-E0002	QLMP-N299-GH002	HLMP-3301-F00DD	HLMP-D105	HLMP-C515
HLMP-1521-E00A2	QLMP-NG98-L00TB	HLMP-3301-FG000	HLMP-D105-M0002	HLMP-C515-L0002
HLMP-1540	QLMP-NL99	HLMP-3301-FI0UK	HLMP-D150	HLMP-C515-L00B2
HLMP-1540-H0002	QLMP-NS33-J0000	HLMP-3316	HLMP-D150-C0002	HLMP-C523
HLMP-1540-H00A1	QLMP-NS33-J00DD	HLMP-3316-HK000	HLMP-D150-C00B2	HLMP-C523-J0002
HLMP-1573	QLMP-NW82	HLMP-3316-HK0CA	HLMP-D154-F0002	HLMP-C615-G0001
HLMP-1700	QLMP-NW83	HLMP-3316-I0002	HLMP-D155	QLMP-3456-EFB00
HLMP-1700-B0002	QLMP-NW91-J0P00	HLMP-3401	HLMP-D155-F0002	QLMP-3623
HLMP-1700-B00A1	QLMP-NW95-J0P00	HLMP-3401-E0002	HLMP-D401	QLMP-3646
HLMP-1700-B00A2	QLMP-NW96-J0P00	HLMP-3401-E00B2	HLMP-D401-EF0FH	QLMP-3647-B0000
HLMP-1700-B00DH	QLMP-Y899-JPP00	HLMP-3416	HLMP-DB25-B0000	QLMP-3678
HLMP-1719-A0002	HLMA-SH05	HLMP-3507	HLMP-DM25-J0000	QLMP-3690
HLMP-1719-A00A1	HLMP-0301	HLMP-3507-D0001	HLMP-DM25-J00B2	QLMP-3691-B0000
HLMP-1719-A00A2	HLMP-0301-C0000	HLMP-3507-D0002	HLMP-DS25-F0000	QLMP-4059
HLMP-1790	HLMP-0401	HLMP-3507-D00B1	HLMP-DS25-F00DD	QLMP-4073
HLMP-1790-A0002	HLMP-0401-B0000	HLMP-3507-D00B2	QLMJ-A017-F00UT	QLMP-C649-G0002
HLMP-1790-A00A1	HLMP-0401-D0002	HLMP-3507-EF000	QLMP-3718-L0000	QLMP-G598
HLMP-1790-A00A2	HLMP-0504	HLMP-3507-EH000	QLMP-3861-K0B00	QLMP-K774-C00FD
HLMP-1790-A00DH	HLMP-0504-B0000	HLMP-3519	QLMP-4735	QLMP-U897
HLMP-K101	HLMP-0504-C0002	HLMP-3519-F0002	QLMP-4748-B0000	HLMP-0805
HLMP-K101-I0002	HLMP-0800	HLMP-3519-GJ0CA	QLMP-C099	

Description and Extent of Change:

The selected manufacturing site has undergone Avago's qualification process and is being qualified as an alternate site.

Reasons for Change:

Assurance of supply to customers.

Effect of Change on Fit, Form, Function, Quality, or Reliability:






There is no change in the fit, form, function and reliability of the device.

Effective Date of Change:

Effective from 15 Nov 2011, there may be combination of product shipments from both current and new manufacturing sites.

Parts identification:-

The product label for parts manufactured in China will mark as "Made In: China" as illustrated below.

	
(1P) Item: Part Number 	STANDARD LABEL LS0002 RoHS Compliant e3 max temp 250C
(1T) Lot: Lot Number 	(Q) QTY: Quantity 
LPN: 	CAT: Intensity Bin 
(9D)MFG Date: Manufacturing Date 	BIN: 
(P) Customer Item: 	
(V) Vendor ID: 	(9D) Date Code: Date Code 
DeptID: 	Made In: China 

Qualification Data:

Qualification data will be available upon request.

These changes have been reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure: Change Control and Customer Notification, A-5962-6052-80, 5957-0258-80 and 971-5507-82.

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.