

## Product Change Notice

**Issue Date: 29 NOV 2011****Change Type:**

Alternative assembly and test site

**Parts Affected:**

SO-16

ACML-7400	ACML-7420	ACPL-331J	ACPL-333J	ACPL-330J	ACPL-332J	ACPL-796J	HCPL-800J
ACML-7410	ACPL-785J						

400 mil DIP-8

ACNW3130	ACNW3190
----------	----------

300 mil DIP-6/DIP-8

4N45	4N46	SL5505A	ACPL-3130	ACPL-4800	ACPL-772L	ACPL-T350	ACPL-790A
ACPL-790B	ACPL-7900	ACPL-7970	ACPL-J313	HCPL-7510	HCPL-7520	HCPL-7560	HCPL-3020
HCPL-3180	HCPL-7723						

All associated options and specials will also be affected.

**Description and Extent of Change:**

Set up of alternative assembly and test site in Thailand.

**Reasons for Change:**

Supply shortage at primary assembly site, alternative site setup as part of business continuity plan.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

All other remaining electrical specifications in datasheet and fit, form, function have not been changed. Appropriate electrical characterization and reliability qualification will be performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

**Effective Date of Change:**

Implementation of the change will be effective from product date code 1148 (YYWW).

**Qualification Data:**

Qualification data is currently being generated for approval. These changes will be reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure.

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.