

CHANGE NOTIFICATION



Linear Technology Corporation
1630 McCarthy Blvd., Milpitas, CA 95035-7417
(408) 432-1900

March 14th, 2012

PCN#: 031412

Dear Sir/Madam:

Subject: Notification of Change to LTC3539 and LTC3539-2 Die

Please be advised that Linear Technology Corporation has made a minor change to the LTC3539/LTC3539-2 die to improve manufacturability. While applications that utilize a feed-forward compensation capacitor as recommended in the product datasheet will be unaffected, circuits not using this component may incur slightly higher output ripple during Burst Mode operation with the new die. There are no associated datasheet specification changes.

This change was qualified by performing characterization over the operating temperature range and thorough in-circuit bench evaluation. Product assembled with the revised die will be shipped with a datecode of approximately 1226.

Should you have any further questions, please feel free to contact me at 408-432-1900 ext. 2519, or by e-mail at NGIRN@Linear.com. If I do not hear from you by April 16th, 2012, we will consider this change to be approved by your company.

Sincerely,

Naib Girn
Quality Assurance Manager

Confidential Statement

This change notice is for Linear Technology's Customers only.
Distribution or notification to third parties is prohibited