

INF 003/23

Early Problem Notification: Burning down of plating production site Wuxi Welnew Microelectronic Co., Ltd., Wuxi, China affecting Infineon's products in packages P-/PG-SC74*/-SOD323*/-SOT143*/-SOT23*, and PG-SC79*/-SOT223*/-SOT323*/-SOT343*/-SOT363*/-SOT89*/-TDSON*/-TSFP*/-TSSOP*



Affected products sold to TOKYO ELECTRON DEVICE LIMITED (4008729)

Sales name	SP number	OPN	Package	Customer part number
BAT 15-099R E6327	SP000010276	BAT15099RE6327HTS A1	PG-SOT143-4-4	
BSS225 H6327	SP001047644	BSS225H6327FTSA1	PG-SOT89-4-2	