

Product End Of Life Notification		Date January 4, 2019
Product	ConnectCore Wi-i.MX51 and ConnectCore Wi-i.MX53 Notice #190104-03	

Reason for Change:

Technical Requirement	Product Transition
Customer Requirement	Product Discontinuation
Quality Improvement	Product Enhancement
Change of Production Location	Other (Brand Change)

Audience	Embedded customers and partners
Reason for change	<p>Digi International is discontinuing the listed part numbers. Products have a LTB (last time buy) component (WiFi) that has no drop-in alternatives.</p> <p>This WiFi component has a LTB date of March 29, 2019, so we ask that the customer places their orders prior to when we must place our component order.</p> <p>These products also have a flash component LTB. There are replacement parts for the flash component, but this may require a firmware updates. See PCN 181206-02 for details. There will be revision updates for the flash component change, which is an update to the PCN.</p>

Discontinued Part Numbers	CC-WMX-LB6B-VM ConnectCore Wi-i.MX51 800 MHz, 2GB ND/512 1xNET CC-WMX-LC47-VM ConnectCore Wi-i.MX512 800 MHz, 128/128 1xNET CC-WMX-MB69-VK ConnectCore Wi-i.MX51 600 MHz, 512/512 2xNET CC-WMX-MB69-VM ConnectCore Wi-i.MX51 600 MHz, 512/512 1xNET CC-WMX-KD69-VK ConnectCore Wi-i.MX53 1GHz, 512/512 2xNET CC-WMX-LD79-VK ConnectCore Wi-i.MX53 800 MHz, 512ND/1GB 2xNET
Replacement Part Numbers	No direct replacement. Contact Digi sales representative for options and guidance.

Timing of Change	Last time buy (LTB) orders must be received by: March 15, 2019 Last time shipments (LTS): September 13, 2019
------------------	---

EOL Terms and Conditions	<ul style="list-style-type: none"> <li>• All LTB Purchase Orders are non-cancellable &amp; non-returnable (NCNR) and subject to final allocation and order confirmation.</li> <li>• Digi reserves the right to make shipments against the total quantity ordered as material becomes available.</li> <li>• Standard warranty policy will apply.</li> </ul>
--------------------------	--

Last Time Buy Parts	Redpine WiFi and Flash
Quality Issues	None
Authorization	Kim Knutsen, Sr. Product Manager, Digi International