

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20160629004 Datasheet for LP2982 Information Only

Date:7/14/2016To:TOKYO ELECTRON DEVICE (DSTR) PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE

LP2982AIM5-5.0/NOPB

CUSTOMER PART NUMBER

null

Technical details of this Product Change follow on the next page(s).

DON Number	20100000					7/14/2010			
PCN Number:	20160629004 PCN Date: 7/14/2016					//14/2016			
Title: Datasheet for									
Customer Contact:	PCN Manager		De	ept: Quality Services					
Change Type:						<u></u>			
Assembly Site		Design	$ \square$	Wafer					
Assembly Process		Data Sheet			Bump Material				
Assembly Materials		Part number change	H		Bump Process				
Mechanical Specifi		Test Site			r Fab Site				
Packing/Shipping/		Test Process	H		Vafer Fab Materials				
Notification Dataila									
Description of Chang	Notification Details								
Description of Chang		ouncing an information on	ly pc	tificatio	.				
The product datasheet(The following change h	s) is being upda	ted as summarized below.							
Texas Instruments						LP2982			
 INSTRUMENTS 		SN\	/S128K	-MARCH 20	00-REVI	SED JUNE 2016			
Changes from Revision J (A	pril 2013) to Revision	К				Page			
Deleted TM symbol from VIP - no longer trademarked; changed word in title from "Regulator" to "LDO"									
http://www.ti.com/proc Reason for Change:	<u>1uct/LP2982</u>								
To more accurately refl	ect device chara	cteristics.							
		nction, Quality or Relia	bility	(nosi	tive	/ negative):			
		cation change announceme							
Changes to product identification resulting from this PCN:									
None.									

Product Affected:						
LP2982AIM5-3.3	LP2982AIM5-3.0/NOPB	LP2982AIM5-5.0/NOPB				
LP2982IM5-3.0/NOPB	LP2982AIM5-3.3/NOPB	LP2982AIM5X-3.0/NOPB				
LP2982AIM5-5.0	LP2982AIM5X-3.3/NOPB	LP2982AIM5X-5.0/NOPB				
LP2982IM5-3.3/NOPB	LP2982IM5-5.0/NOPB	LP2982IM5X-3.0/NOPB				
LP2982IM5X-3.3/NOPB	LP2982IM5X-5.0/NOPB					

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com