



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

**Notification# 20160901001
Datasheet update for TLV237x
Information Only Datasheet**

Date: 9/14/2016
To: TOKYO ELECTRON DEVICE (DSTR) PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20160901001
Information Only Datasheet
Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
TLV2371IDR	null
TLV2374ID	null
TLV2374IPW	null
TLV2374IPWR	null
TLV2372IDGK	null
TLV2371IDBVT	null
TLV2372IDR	null
TLV2372IDGKR	null

Technical details of this Product Change follow on the next page(s).

Notification Number:	20160901001	Notification Date:	Sept. 14, 2016
Title:	Datasheet update for TLV237x		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
☐	Assembly Site	☐	Design
☐	Assembly Process	☒	Data Sheet
☐	Assembly Materials	☐	Part number change
☐	Mechanical Specification	☐	Test Site
☐	Packing/Shipping/Labeling	☐	Test Process
☐		☐	Wafer Bump Site
☐		☐	Wafer Bump Material
☐		☐	Wafer Bump Process
☐		☐	Wafer Fab Site
☐		☐	Wafer Fab Materials
☐		☐	Wafer Fab Process

Notification Details	
Description of Change:	
Texas Instruments Incorporated is announcing an information only notification.	
The product datasheet(s) is being updated as summarized below.	
The following change history provides further details.	
 TLV2370, TLV2371, TLV2372 TLV2373, TLV2374, TLV2375 SLOS270F – MARCH 2001 – REVISED AUGUST 2016	
Changes from Revision E (May 2016) to Revision F	
	Page
• Changed names of pins 2 and 3 in TLV2372 D, DGK, and P packages pinout diagram	4
The datasheet number will be changing.	
Device Family	Change From: Change To:
TLV237x	SLOS270E SLOS270F
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/TLV2370	

Reason for Change:			
To more accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
TLV2370ID	TLV2371IDR	TLV2373IDG4	TLV2374IPW
TLV2370IDBVR	TLV2371IDRG4	TLV2373IDGS	TLV2374IPWG4
TLV2370IDBVRG4	TLV2371IP	TLV2373IDGSG4	TLV2374IPWR
TLV2370IDBVT	TLV2371IPE4	TLV2373IDGSR	TLV2374IPWRG4
TLV2370IDBVTG4	TLV2372ID	TLV2373IDGSRG4	TLV2375ID
TLV2370IDG4	TLV2372IDG4	TLV2373IDR	TLV2375IDG4
TLV2370IDR	TLV2372IDGK	TLV2373IDRG4	TLV2375IDR

TLV2370IP	TLV2372IDGKG4	TLV2373IN	TLV2375IDRG4
TLV2370IPE4	TLV2372IDGKR	TLV2374-W	TLV2375IN
TLV2371ID	TLV2372IDGKRG4	TLV2374ID	TLV2375IPW
TLV2371IDBVR	TLV2372IDR	TLV2374IDG4	TLV2375IPWG4
TLV2371IDBVRG4	TLV2372IDRG4	TLV2374IDR	TLV2375IPWR
TLV2371IDBVT	TLV2372IP	TLV2374IDRG4	TLV2375IPWRG4
TLV2371IDBVTG4	TLV2372IPE4	TLV2374IN	
TLV2371IDG4	TLV2373ID	TLV2374INE4	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com