

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20190522001 Datasheet for INA128, INA129 Information Only

Date:May 29, 2019To:TOKYO ELECTRON DEVICE (DSTR) PCN

Dear Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN team (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
INA128P	null
INA128U	null
INA128UA	null
INA128UA/2K5	null
INA128UAE4	null
INA128U/2K5	null
INA128UAG4	null
INA128UA/2K5G4	null

Technical details of this Product Change follow on the next page(s).

PCN	Number:	20190522001	P	CN Date:	May	/ 29, 2	019	
Title	e: Datasheet for	INA128, INA129	9					
Cus	tomer Contact:	PCN Manager			De	ept:	Quality Services	
Cha	nge Type:							
	Assembly Site		Design				r Bump Site	
	Assembly Process		Data Sheet				r Bump Material	
Assembly Materials			Part number	change	Ц		r Bump Process	
Mechanical Specification			Test Site				r Fab Site	
Packing/Shipping/Labeling		Test Process		\square		r Fab Materials		
Notification Details								
Des	cription of Change		tincation	Details				
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.								
	Texas Instruments			s	BOS05	51E - OCTO	INA128, INA129 BER 1995-REVISED APRIL 2019	
SBOS051E – OCTOBER 1995–REVISED APRIL 2019								
Changes from Revision D (January 2018) to Revision E Page								
·							1	
•	Added Device Comparison	n Table						
	datasheet number v	vill be changing.						
De	vice Family		Change Fr	om:		Change To:		
INA	INA128, INA129		SBOS051D)		SBOS051E		
These changes may be reviewed at the datasheet links provided.								
	2 ,		uatasheet iii	iks provided.				
http://www.ti.com/product/INA128								
	son for Change:							
	accurately reflect dev							
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):								
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.								
	nges to product id	lentification re	esulting from	m this PCN:				
None.								
Pro	duct Affected:							
INA	A128P	INA128U/2K5		INA128UA/2K	5E4		INA128UG4	
INA	A128PA	INA128U/2K5G	4	INA128UA/2K	1		INA128UA/2K5	
INA	A128PG4	INA128UA		INA128UAE4			INA128UAG4	
	A128U							
For questions regarding this notice, e-mails can be sent to the contacts shown below or your local Field Sales Representative.								

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
WW PCN Team	PCN ww admin team@list.ti.com